
















Шкаф Деос 2








 Ø6,3x50 mm A1 x 32	 Ø12 mm A2 x 32	 4 mm A3 x 1	 Ø4x16 mm D1 x 28	 Ø4,2x25 mm D2 x 4
 Ø4x30 mm D3 x 2	 Ø1,6x20 mm F x 82	 Ø8x36 mm G x 38	 H x 2	 K x 1
 M x 4	 Ø15 mm N x 4	 50g R x 1		




Box 1/3

418x400x16 mm




Fittings & Tools

418x400x16 mm




Box 2/3


450x420x16 mm




350x100x16 mm




390x348x3 mm




360x100x16 mm




360x100x16 mm




350x100x16 mm




364x445x16 mm




418x400x16 mm




1904x400x16 mm



1904x400x16 mm



1842x444x3 mm




Box 3/3


1097x147x16 mm



179x445x16 mm




70x418x16 mm



1





D1 x 6








K.1 x 1




K.2 x 1



2



3




A1 x 4






A2 x 4





A3 x 1






G x 4



4



⚠ XX=YY≅90°



5



D1 x 16




D2 x 2





H x 1




M.1 x 4



M.2 x 4





6




G x 8





R x 1



7




G x 2





8




D2 x 2





H x 1




9



F x 24



⚠ XX=YY≅90°



10





D1 x 6



K.3 x 1





K.4 x 1



11



D3 x 2



12

