










 Ø6,3x50 mm <b>A1 x 16</b>	 Ø12 mm <b>A2 x 16</b>	 4 mm <b>A3 x 1</b>	 Ø4x16 mm <b>D1 x 20</b>	 Ø4,2x25 mm <b>D2 x 4</b>
 Ø1,6x20 mm <b>F x 49</b>	 Ø8x36 mm <b>G x 12</b>	 <b>H x 2</b>	 Ø5x16 mm <b>L x 16</b>	 <b>M x 5</b>
 Ø15 mm <b>N x 4</b>				




# Box 1


1842x444x3 mm




418x400x16 mm




450x419x16 mm




418x390x16 mm




544x445x16 mm




1904x400x16 mm




1904x400x16 mm




418x400x16 mm



1281x445x16 mm



70x418x16 mm



Fittings & Tools

1



A1 x 12





A2 x 12




A3 x 1



G x 8



2




A1 x 4





A2 x 4





A3 x 1






G x 4



3



⚠ XX=YY≅90°





4



D1 x 20



D2 x 4




H x 2



L x 16



M.1 x 5



M.2 x 5

