














 Ø6,3x50 mm A1 x 54	 Ø12 mm A2 x 54	 4 mm A3 x 1	 Ø15x12 mm B1 x 18	 Ø5x44 mm B2 x 18
 Ø20 mm B3 x 18	 Ø4x16 mm D1 x 72	 Ø3x25 mm D2 x 6	 Ø1,6x25 mm F x 204	 Ø8x36 mm G x 51
 K x 6	 N x 5	 745 mm O1 x 2	 Z x 6	




Box 1/3


747x424x16 mm




747x424x16 mm




747x424x16 mm



400x120x16 mm




400x120x16 mm




Fittings & Tools

Box 2/3


773x297x3 mm




548x406x3 mm




1199x440x16 mm





1199x424x16 mm




575x110x16 mm




60x575x16 mm




575x70x16 mm




60x575x16 mm



60x575x16 mm




518x120x16 mm




Box 3/3






223x594x16 mm











223x594x16 mm








1











2




3



4



5




A1 x 4




A2 x 4



A3 x 1



6




A1 x 4



A2 x 4




A3 x 1



x 2

7




A1 x 4



A2 x 4




A3 x 1



x 2

8





A1 x 6




A2 x 6



A3 x 1



9





A1 x 6




A2 x 6



A3 x 1






10













B2 x 6











G x 7






11



12



⚠ XX=YY≅90°



13





D1 x 36



K.1 x 6




K.2 x 6




K.2

K.1



14



A1 x 24




A2 x 24



A3 x 1




B1 x 12



x 6

15






B2 x 6



B3 x 6










G x 12




x 3


16





x 3



17



! $XX=YY \cong 90^\circ$



x 6

18





D1 x 18



K.3 x 3



K.4 x 3



x 3

19





D1 x 18



K.3 x 3



K.4 x 3



x 3

20

