



PARTS LIST

1. - 1 Pc



2. - 1 Pc



3. - 4 Pcs



4. - 4 Pcs



FITTINGS

A. -M8 -4 Pcs



C. -M8-1 Pc



D. -M8-8 Pcs



E. -M8-8 Pcs



F.-M8 -4 Pcs




G. -4 Pcs




B. -M8-4 Pcs




1




2



3



4



5

The table is ready to be used, please turn it over!

