











 Ø6,3x50 mm A1 x 8	 Ø12 mm A2 x 8	 4 mm A3 x 1	 Ø4x30 mm D x 4	 Ø1,6x25 mm F x 32
 Ø5x16 mm L x 8	 M x 4	 682 mm O x 2	 Ø8x30 mm T x 2	 U1 x 2
 U2 x 2				




Box


715x280x16 mm




715x280x16 mm




768x280x16 mm




768x260x16 mm




714x265x3 mm



714x265x3 mm






714x265x3 mm




Fittings & Tools


1




2





F x 32



O x 2



$XX=YY\cong 90^\circ$




3









L x 8



M.1 x 4




M.2 x 4









D x 4



U1 x 2




U2 x 2








T x 2



Ø8



1



2

