












 Ø6,3x50 mm <b>A1 x 8</b>	 Ø12 mm <b>A2 x 8</b>	 4 mm <b>A3 x 1</b>	 Ø3x16 mm <b>D1 x 20</b>	 Ø4x16 mm <b>D2 x 8</b>
 Ø8x30 mm <b>E x 2</b>	 Ø1,6x25 mm <b>F x 16</b>	 Ø8x36 mm <b>G x 4</b>	 <b>M x 4</b>	 <b>N x 4</b>
 <b>U x 4</b>	 <b>Y x 2</b>			




### Box

450x699x16 mm




1 x1

450x699x16 mm




2 x1

800x450x16 mm



3 x1

768x80x16 mm



4 x1

200x200x3 mm



5 x2

768x80x16 mm









7 x1

Fittings & Tools







N x4

1





2





3

D1 x 16 F x 16 Nx4



4

M.1 x 4 M.2 x 4







5



D1 x 4







Y x 2




i



D2 x 4








E x 2



Ø8



1



2

