












 Ø6,3x50 mm A1 x 8	 Ø12 mm A2 x 8	 4 mm A3 x 1	 Ø3x16 mm D1 x 20	 Ø4x16 mm D2 x 8
 Ø8x30 mm E x 2	 Ø1,6x25 mm F x 16	 Ø8x36 mm G x 4	 M x 4	 N x 4
 U x 4	 Y x 2			




Box


450x699x16 mm




450x699x16 mm




800x450x16 mm




768x80x16 mm




200x200x3 mm





768x80x16 mm






Fittings & Tools








3



⚠ XX=YY≅90°



4







5



D1 x 4







Y x 2



i




D2 x 4







Ex 2



Ø8



1



2

