













 Ø6,3x50 mm <b>A1 x 14</b>	 Ø12 mm <b>A2 x 14</b>	 4 mm <b>A3 x 1</b>	 Ø3x16 mm <b>D1 x 20</b>	 Ø4x16 mm <b>D2 x 6</b>
 Ø4x30 mm <b>D3 x 9</b>	 Ø8x30 mm <b>E x 2</b>	 Ø1,6x25 mm <b>F x 16</b>	 Ø8x36 mm <b>G x 4</b>	 <b>M x 2</b>
 <b>N x 4</b>	 <b>U x 3</b>	 <b>Y x 2</b>		




# Box


450x699x16 mm




450x699x16 mm




880x450x16 mm




848x80x16mm




715x80x16 mm




715x80x16 mm




715x80x16 mm




200x200x3 mm




848x80x16 mm





715x80x16 mm




Fittings & Tools





1






2






3



⚠ XX=YY≅90°





4



5




D3x 6





6



M.1 x 2




M.2 x 2










7


  
D1 x 4






  
Y x 2







  
D3 x 3

  
D2 x 3






①




②








Ex 2



Ø8



1



2

