











 Ø6,4x50 mm A1 x 16	 Ø12 mm A2 x 16	 4 mm A3 x 1	 Ø15x12 mm B1 x 4	 Ø5x44 mm B2 x 4
 Ø20 mm B3 x 4	 Ø4x16 mm D1 x 16	 Ø1,6x25 mm F x 26	 Ø8x36 mm G x 22	 M x 4
 Ø15 mm N x 4				




Box 1


698x388x3 mm




80x668x16 mm




668x70x16mm




60x600x16 mm




329x330x16 mm




60x304x16 mm




329x310x16 mm




701x380x16mm




358x379x16 mm



358x379x16 mm







701x380x16 mm










Fittings & Tools


1



2



3




A1 x 2




A2 x 2



A3 x 1



4




A1 x 2





A2 x 2




A3 x 1



G x 6




5





A1 x 4



A2 x 4




A3 x 1



6




B1 x 4











B2 x 4




B3 x 4



G x 6




7




F x 26



N x 4




$XX=YY \cong 90^\circ$



8



D1 x 16



M.2 x 4



M.1 x 4

